


Attachment 5  
**Scenario 1**



Scenario 1  
 Selected Sections for Treatment  
 All years (Y1-Y3)



FIGURE  
 1/4


JOB NUMBER  
 910.07.30

DRAWN  
 Alberto Rocher

DATE  
 03/06/2024

REVISED  
 Timin Punnackal

APPROVED  
 Vivek Jha



Scenario 1  
Selected Sections for Treatment  
Year 1



FIGURE  
1/4


JOB NUMBER  
910.07.30

DRAWN  
Alberto Rocher

DATE  
03/06/2024

REVISED  
Timin Punnackal

APPROVED  
Vivek Jha



Scenario 1  
Selected Sections for Treatment  
Year 2



FIGURE  
3/4



JOB NUMBER  
910.07.30

DRAWN  
Alberto Rocher


DATE  
03/06/2024

REVISED  
Timin Punnackal

APPROVED  
Vivek Jha



**Scenario 1**  
**Selected Sections for Treatment**  
 Year 3



**FIGURE**  
**4/4**

JOB NUMBER  
910.07.30

DRAWN  
Alberto Rocher


DATE  
03/06/2024

REVISED  
Timin Punnackal


APPROVED  
Vivek Jha

---

**Scenario 1 Treated Sections: Year 1**



- Current Projects
- Slurry Seal & Crack Seal  
+4% Base Repairs




**Scenario 1**  
**Selected Sections for Treatment**  
 Year 1




FIGURE  
1/5

JOB NUMBER 910.07.30	DRAWN Alberto Rocher	DATE 3/6/2024	REVISED Timin Punnackal	APPROVED Vivek Jha
-------------------------	-------------------------	------------------	----------------------------	-----------------------



- Current Projects
- 3" Mill and Thick Overlay +6% Base Repairs
- Slurry Seal & Crack Seal +4% Base Repairs




Scenario 1  
Selected Section for Treatment  
Year 1



FIGURE  
2/5

JOB NUMBER 910.07.30	DRAWN Alberto Rocher	DATE 3/6/2024	REVISED Timin Punnackal	APPROVED Vivek Jha
-------------------------	-------------------------	------------------	----------------------------	-----------------------



BIRNEY (ALICE M) ELEMENTARY SCHOOL

- Current Projects
- 3" Mill and Thick Overlay +6% Base Repairs
- Slurry Seal & Crack Seal +4% Base Repairs



Scenario 1  
Selected Sections for Treatment  
Year 1



FIGURE  
3/5


JOB NUMBER  
910.07.30

DRAWN  
Alberto Rocher


DATE  
3/6/2024

REVISED  
Timin Punnackal

APPROVED  
Vivek Jha



- Current Projects
- 3" Mill and Thick Overlay +6% Base Repairs
- Slurry Seal & Crack Seal +4% Base Repairs




**Scenario 1**  
**Selected Sections for Treatment**  
 Year 1




FIGURE  
4/5

JOB NUMBER 910.07.30	DRAWN Alberto Rocher	DATE 3/6/2024	REVISED Timin Punnackal	APPROVED Vivek Jha
-------------------------	-------------------------	------------------	----------------------------	-----------------------



- Current Projects
- 3" Mill and Thick Overlay +6% Base Repairs
- Slurry Seal & Crack Seal +4% Base Repairs




**Scenario 1**  
**Selected Sections for Treatment**  
 Year 1





FIGURE  
5/5

---

**Scenario 1 Treated Sections: Year 2**



- Current Projects
- Mill and Thick Overlay +6% Base Repairs
- Slurry Seal & Crack Seal +4% Base Repairs





**Scenario 1**  
**Selected Sections for Treatment**  
 Year 2



FIGURE  
1/4

JOB NUMBER 910.07.30	DRAWN Alberto Rocher	DATE 3/6/2024	REVISED Timin Punnackal	APPROVED Vivek Jha
-------------------------	-------------------------	------------------	----------------------------	-----------------------



**Scenario 1**  
**Selected Sections for Treatment**  
 Year 2




FIGURE  
 2/4



JOB NUMBER  
 910.07.30

DRAWN  
 Alberto Rocher


DATE  
 3/6/2024

REVISED  
 Timin Punnackal

APPROVED  
 Vivek Jha




**Scenario 1**  
**Selected Sections for Treatment**  
 Year 2




**FIGURE**  
**3/4**

JOB NUMBER 910.07.30	DRAWN Alberto Rocher	DATE 3/6/2024	REVISED Timin Punnackal	APPROVED Vivek Jha
-------------------------	-------------------------	------------------	----------------------------	-----------------------



- Current Projects
- 3" Mill and Thick Overlay +6% Base Repairs
- Slurry Seal & Crack Seal +4% Base Repairs



**Scenario 1**  
**Selected Sections for Treatment**  
 Year 2



FIGURE  
4/4

JOB NUMBER  
910.07.30

DRAWN  
Alberto Rocher



DATE  
3/6/2024

REVISED  
Timin Punnackal

APPROVED  
Vivek Jha

---

**Scenario 1 Treated Sections: Year 3**



Scenario 1  
Selected Sections for Treatment  
Year 3



FIGURE  
1/2



JOB NUMBER  
910.07.30

DRAWN  
Alberto Rocher

DATE  
3/6/2024

REVISED  
Timin Punnackal

APPROVED  
Vivek Jha



Scenario 1  
 Selected Sections for Treatment  
 Year 3




FIGURE  
 2/2

JOB NUMBER 910.07.30	DRAWN Alberto Rocher	DATE 3/6/2024	REVISED Timin Punnackal	APPROVED Vivek Jha
-------------------------	-------------------------	------------------	----------------------------	-----------------------